



Wymiar	M 3*	M 4	M 5	M 6	M 8
$e_{\max 314/315}$	-/16	21/20	26.5/26	32/33	38/39
$h_{\max}$	8	11/10.5	13	16/17	19/20
$m_{\max}$	4	4.6	6.5	8	10
$d_{2 \max}$	6	8	11	13	16
$d_{3 \max}$	5	7	9	11	12.5

Wymiar	M 10	M 12	M 16	M 20	M 24
$e_{\max 314/315}$	50/51	66/65	73	90	110
$h_{\max}$	24/25	32/33.5	37.5	46.5	56.5
$m_{\max}$	12	14	17	21	25
$d_{2 \max}$	20	23	29	35	44
$d_{3 \max}$	16.5	19.5	23	29	37.5

