


DIN (ISO)
913
(4026)



Wymiar	M 1.4	M 1.6	M 2	M 2.5	M 3	M 4	M 5	M 6
s	0.7	0.7	0.9	1.3	1.5	2	2.5	3
$d_{p \max}/d_{t \max}$	0.45	0.8	1	1.5	2	2.5	3.5	4

Wymiar	M 8	M 10	M 12	M 14	M 16	M 20	M 24
s	4	5	6	6	8	10	12
$d_{p \max}$	5.5	7	8.5	10	12	15	18

