


DIN (ISO)

914
(4027)



| Wymiar | M 1.4 | M 1.6 | M 2 | M 2.5 | M 3 | M 4 | M 5 | M 6 |
|-------------------------------------|-------|-------|-----|-------|-----|-----|-----|-----|
| s | 0.7 | 0.7 | 0.9 | 1.3 | 1.5 | 2 | 2.5 | 3 |
| $d_p \text{ max} / d_t \text{ max}$ | 0.45 | 0.8 | 1 | 1.5 | 2 | 2.5 | 3.5 | 4 |

| Wymiar | M 8 | M 10 | M 12 | M 14 | M 16 | M 20 | M 24 |
|-------------------|-----|------|------|------|------|------|------|
| s | 4 | 5 | 6 | 6 | 8 | 10 | 12 |
| $d_p \text{ max}$ | 5.5 | 7 | 8.5 | 10 | 12 | 15 | 18 |

