


ISO 4017



Wymiar	M 3	M 4	M 5	M 6	M 7	M 8	M 10	M 12	M 14
$S_{ISO/din}$	5.5	7	8	10	11	13	16/17	18/19	21/22
k	2	2.8	3.5	4	4.8	5.3	6.4	7.5	8.8
a_{max}	1.5	2.1	2.4	3	3	3.75	4.5	5.25	6
b_1	12	14	16	18	20	22	26	30	34
b_2	-	-	22	24	26	28	32	36	40
b_3	-	-	-	-	-	-	45	49	53

Wymiar	M 16	M 18	M 20	M 22	M 24	M 27	M 30	M 33	M 36
$S_{ISO/din}$	24	27	30	34/32	36	41	46	50	55
k	10	11.5	12.5	14	15	17	18.7	21	22.5
a_{max}	6	7.5	7.5	7.5	9	9	10.5	10.5	12
b_1	38	42	46	50	54	60	66	72	78
b_2	44	48	52	56	60	66	72	78	84
b_3	57	61	65	69	73	79	85	91	97

Wymiar	M 39	M 42	M 45	M 48	M 52	M 56	M 64
$S_{ISO/din}$	60	65	70	75	80	85	95
k	25	26	28	30	33	35	40
a_{max}	12	13.5	13.5	15	15	16.5	18
b_1	84	90	96	102	-0	-0	-0
b_2	90	69	102	108	116	124	140
b_3	103	109	115	121	129	137	153

