



| Wymiar | M 3 | M 4 | M 5 | M 6 | M 8 | M 10 | M 12 | M 16 |
|--------|------|------|------|------|------|------|------|------|
| d_k | 5.7 | 7.6 | 9.5 | 10.5 | 14 | 17.5 | 21 | 28 |
| d_c | 6.65 | 8.85 | 11.2 | 13 | 17.1 | 21 | 23.6 | - |
| k | 1.65 | 2.2 | 2.75 | 3.3 | 4.4 | 5.5 | 6.6 | 8.8 |
| s | 2 | 2.5 | 3 | 4 | 5 | 6 | 8 | 10 |
| TORX | T10 | T20 | T25 | T30 | T40 | T50 | T50 | - |

