


DIN 6885 A



Wymiar	2	3	4	5	6	8	10
h	2	3	4	5	6	8	10
for shafts $\varnothing d/d_1$	6-8	8-10	10-12	12-17	17-22	22-30	30-38

Wymiar	12	14	16	18	20	22	25
h	12	14	16	18	20	22	25
for shafts $\varnothing d/d_1$	38-44	44-50	50-58	58-65	65-75	75-85	85-95

Wymiar	28	32	36	40	45
h	28	32	36	40	45
for shafts $\varnothing d/d_1$	95-110	110-130	130-150	150-170	170-200

